

Report of results of car state inspection

78 - 01.08.2015 13:50:41

Client name
Phone number
Mark **LIFAN**
Model **X60**
Year **2012 - 2013**
Car number
VIN **000000000000**
Mileage **0 km**
Master name

Delphi MT 22.1

ScanDoc data (parameters/identification)

Name	Value
	798,2 /
	74° C
A/C system refrigerant test complete	
A/C system refrigerant test supported	
Comprehensive component monitoring tests complete	
Comprehensive components monitoring	
Enhanced evaporative purge system test complete	
Enhanced evaporative purge system test supported	
Exhaust camshaft position variance	0
Fuel pulse width	4,21
Fuel pump command	
Fuel system monitoring tests complete	
Heated catalyst test supported	
Intake camshaft position variance	0
Mileage After Fault	0
Misfire monitoring tests complete	
O2 sensor heater test supported	
	17,65%
	0
	49,80

"Check engine"		0
		26
2 1,	1	0,905
2 2,	1	1,275
(MAP)		44
		99,63
N1		14,51
		8,63
		762,5 /
DTC	-	02 64
		2
		0,00Grad kw
1		0,00%
		14,2
, 1		1,0Grad kw
		6,27
		EOBD ()
02		1 1 2 1
		4,34 /
		45,10%
		0,00
, 1		0,00
/ , 1		14,6:1

Signature _____

Stamp